

**Facility Name:** Utica Resource Operating, LLC – Garvin Well Pad

**Facility Location:** 39.56399, -81.5081, Wills Township, Ohio

**Date of Inspection:** April 18, 2019

**APPENDIX A: DIGITAL IMAGE/VIDEO LOG**

<b>1. Inspector Name:</b> Victoria Nelson	<b>2. Dates of Inspection:</b> April 18, 2019
<b>3. Company/Facility Name:</b> Utica Resource Operating, LLC – Garvin Well Pad	<b>4. Street Address, City, State:</b> 39.56399, -81.5081, Wills Township, Ohio
<b>5. Number of Images and Videos:</b> 9	<b>6. Archival Record Location:</b> C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2416.mp4	4/18/2019	Emissions from water condensate tank thief hatch
2	MOV_2417.mp4	4/18/2019	Emissions from Tank 2269 thief hatch
3	MOV_2418.mp4	4/18/2019	Emissions from Tank 2267 thief hatch
4	MOV_2419.mp4	4/18/2019	Emissions from combustor - combustor was not operating
5	MOV_2420.mp4	4/18/2019	Emissions from 2-H Separator during dump

Image Number	File Name	Date and Time (Eastern Time)	Latitude and Longitude	Description of Image
1	P4180045.JPG	4/18/2019 4:34:39 PM	39.56322, -81.507512	Line to combustor in gully
2	P4180046.JPG	4/18/2019 4:35:12 PM	39.563047, -81.507435	View of combustor, access road, and tank battery
3	P4180047.JPG	4/18/2019 4:36:50 PM	39.563405, -81.507602	Line leading to base of combustor
4	P4180048.JPG	4/18/2019 4:36:55 PM	39.563405, -81.507602	Line from combustor leading to separators